






M1412




















H = 175 - 245 mm	H1 →	5	---
H = 140 - 175 mm	H2 →	3	
H = 125 - 140 mm	H3 →	3	
H = 95 - 115 mm	H4 →	3	




L = 140 - 210 mm	L1 →	5	---
L = 110 - 140 mm	L2 →	4	
L = 90 - 110 mm	L3 →	4	
L = 80 - 100 mm	L4 →	4	


H2**H3****H4**

L2**L3****L4**


1




2








3




4




5




6




7





8



9



10



$$X = L - 35\text{mm}$$

